

SERVICE BULLETIN INDEX

TP85-1

FCSC P/N 108440-/109300- Boeing P/N 60B00158

S. B. No.	Title	Effective Date
TP85-1-29-01	Mounting Lug Rework	Sep. 16, 1968
TP85-1-29-02	Trigger Plate Replacement	Mar. 15, 1970
TP85-1-29-03	Shutoff Valve Diaphragm Assembly	Apr. 30, 1970
TP85-1-29-04	Shutoff Valve Actuator Clearance Hole	Apr. 30, 1970
TP85-1-29-05	Acceleration Controller Bracket	May 05, 1970
TP85-1-29-06	Sight Glass Plug Replacement	Apr. 06, 1970
TP85-1-29-07	Oil Fill Cap Assy Replacement Replaced By S.B. TP85-1-29-08	May 07, 1970
TP85-1-29-08	Oil Fill Cap Assy Replacement	Aug. 04, 1970
TP85-1-29-09	Electrical Component Relocation	Feb. 22, 1970
TP85-1-29-10	Indicator Switch Relocation	Nov. 12, 1970
TP85-1-29-11	Shutoff Valve Air Filter Replacement Rev 1	Feb. 22, 1971 Aug. 28, 1972
TP85-1-29-12	Rotor Assy Rework, Rev.2	Oct. 27, 1972
TP85-1-29-13	Overspeed Trip Assy Rework	Dec. 01, 1971
TP85-1-29-14	Overspeed Trip Arm Washer	Jan. 05, 1972
TP85-1-29-15	Pneumatic Solenoid Valve Replacement	Feb. 15, 1973
TP85-1-29-16	Shutoff Actuator Diaphragm Replacement Rev 1	Apr. 01, 1973 May 25, 1973
TP85-1-29-17	Shutoff Valve Butterfly Seal Ring	Apr. 01, 1973
TP85-1-29-18	Time Delay Relay With Heat Shield	Sep. 01, 1974
TP85-1-29-19	Shutoff & Control Valve Bearings	Nov. 20, 1974
TP85-1-29-20	Oil Level Indicator Inspection	Feb. 12, 1975
TP85-1-29-21	Approved Lubricating Oil Rev A Rev B	Sep. 28, 1970 Sep. 01, 1987 Jun 26, 2001
TP85-1-29-22	Cartridge Assy Modification Rev 1	Apr. 30, 1976 Oct. 14, 1976
TP85-1-29-23	Rotor Assy Gasket Rev 1	Apr. 30, 1976 Oct. 14, 1976

S. B. No.	Title	Effective Date
TP85-1-29-24	Rotor Assy Seal Housing Rev 1	Apr. 30, 1976 Oct. 14, 1976
TP85-1-29-25	Control Valve Assy Butterfly Bearings	Sep. 29, 1976
TP85-1-29-26	Turbine Oil Level Inspection	Oct. 01, 1976
TP85-1-29-27	Output Gear Inspection	Oct. 14, 1976
TP85-1-29-28	Wiring Harness Repair	Oct. 15, 1976
TP85-1-29-29	Upper Gear Housing Mounting Lug Repair Rev A	May 31, 1977 Sep 01, 1987
TP85-1-29-30	Solenoid Coil Replacement	Oct. 31, 1977
TP85-1-29-31	Time Delay Relay (Connector Type)	Oct. 01, 1979
TP85-1-29-32	Solenoid Valve (Connector Type)	Oct. 01, 1979
TP85-1-29-33	Pressure Switch (Connector Type)	Oct. 01, 1979
TP85-1-29-34	Terminal Block Elimination	Oct. 01, 1979
TP85-1-29-35	Overspeed Trip Valve Boot	Oct. 01, 1979
TP85-1-29-36	Improved Governor Control Spring	Mar. 01, 1981
TP85-1-29-37	109565 Tube Shield	Nov. 01, 1981
TP85-1-29-38	Attaching Hardware Rev A	Jun. 01, 1983 Nov. 01, 1986
TP85-1-29-39	Incorporation Of In-Line Filters	Jul 01, 1987
TP85-1-29-40	Solenoid Valve Port Reversal	May 01, 1987
TP85-1-29-41	Electrical Component Improvement Rev A	Aug. 01, 1987 May 20, 1994
TP85-1-29-42	Acceleration Controller Valve & Seat Rev A	Aug. 01, 1987 Aug. 07, 1996
TP85-1-29-43	Exhaust Header Oil Leakage Rev A	Dec. 10, 1988 May 01, 1989
TP85-1-29-44	Turbine Rotor Oil Seal Replacement Rev A	Mar. 17, 1992 Feb. 01, 1994
TP85-1-29-45	In-Line Filter Replacement	Apr. 08, 1992
TP85-1-29-46	Governor Bearing Replacement	Jan. 31, 1994
TP85-1-29-47	Governor Orifice Replacement Rev. A	Apr. 01, 1994 Jun. 26, 1997
TP85-1-29-48	Solenoid Nut Replacement	Mar. 17, 1995
TP85-1-29-49	Upper Gear Housing Replacement	Jul. 22, 1996
TP85-1-29-50	Modulating Valve Seal Replacement	Jun. 12, 1997

S. B. No.	Title	Effective Date
TP85-1-29-51	Oil Manifold Housing Rework Rev. A	Jun. 13, 1997 Oct 10.2003
TP85-1-29-52	Nozzle Wear Prevention	Jun. 13, 1997
TP85-1-29-53	S/O Valve Actuator Spring Inspection	May 19, 1999
TP85-1-29-54	Governor Bearing Replacement	June 1, 2000
TP85-1-29-55	In-Line Filter Relocation	June 20, 2002